

COMPLEX ELECTRONICS GUIDE

A GROWING OFFERING OF COMPLEX ELECTRONICS TO HELP YOU KEEP PACE WITH CHANGING TECHNOLOGY



NEW PRODUCTS • NEW SOLUTIONS • NEW OPPORTUNITIES


CONTENTS



A GROWING OFFERING OF COMPLEX ELECTRONICS

Todays' vehicles rely on a host of microprocessors linked by 5 miles of wiring running over 100 million lines of computer code – just to shift into 'drive'.

Just to shift into 'drive'. Dorman leads the Aftermarket with its development and introduction of high-quality solutions for replacement complex electronic modules.



Electronic components now account for 40% of today's automotive production costs

To keep pace with advances in today's electronics, Dorman's Development Teams concentrate on key aspects of module development:

- Software re-engineering
- Encryption
- Vehicle communication protocols
 Flashing solutions

The result is Dorman's comprehensive Complex Electronics offering – designed to save time and money by eliminating a trip to the OE Dealer for both parts and programming.

PAGE THROUGH OUR INNOVATIONS SAFETY CONVENIENCE OS-08 O9-11 D04 O5-08 O9-11 D04 O5-08 O9-11 D04 O5-08 O9-11 D04 O5-08 O9-11 O5-08 O5-08 O9-11 O5-08 O

ABS CONTROL MODULES

To help eliminate the original failure mode, an external diode has been added along with complete reflowing of solder joints

Covered by Dorman's Limited Lifetime Warranty

Failure Mode: Water intrusion



ALSO AVAILABLE

599-705 Chevrolet Silverado 1500 2002-99, GMC Sierra 1500 2002-99

599-726

Chevrolet Blazer 2005-00, Chevrolet S10 2004-00, GMC Jimmy 2001-00, GMC Sonoma 2004-00

599-710

Chevrolet Avalanche 1500 2004-03, Chevrolet Silverado 1500 2004-03, GMC Sierra 1500 2004-03 **599-701** Chevrolet 2002-00, GMC 2002-00

AIR BAG IMPACT SENSORS

ALSO KNOWN AS: CRASH SENSORS

NEW

Plug and play design for an easy installation -No reprogramming necessary

590-200 GM CK Truck Series 2007-05



Failure Mode: Water intrusion and/or collision damage

XENON HEADLIGHT CONTROL MODULES

THE AFTERMARKET LEADER IN XENON HID HEADLAMP BALLASTS WITH OVER 10 SKUS AVAILABLE

Restores headlights to proper operation

Failure Mode: Failure results in headlights not illuminating



601-056 NEW

Various BMW, Land Rover, Ford, GM, Hyundai, Mercedes and VW models, 2013-02







SAFETY

AIRBAG

OCCUPANT DETECTION SENSOR

Popular replacement part due to highly failure prone original sensor in a large population of vehicles

DORMAN ENGINEERED: Upgraded gasket design prevents water intrusion



Failure Mode: Water intrusion and electrical faults

601-004 Most Toyota and Lexus models 2015-05

ABS CONTROL MODULE

Fully Remanufactured and vehicle simulator tested for quality assurance

Updated with more durable main pump transistors to help prevent pump relay burnout

100% replacement of gaskets, gromets and seals

EXCLUSIVE

Failure Mode: Water intrusion



POWER STEERING PUMP

Restores hydraulic pressure required for power steering

100% replacement with all new armatures, seals, gaskets, bearings

Failure Mode: Failure results in loss of power steering

599-950 Mini Cooper 2008-02



KEY FOBS

THE AFTERMARKET'S FASTEST GROWING KEYLESS REMOTE COVERAGE

Simple to Program: Programming new remote to existing vehicle takes less than 5 minutes

All Dorman Keyless Entry Remotes include everything needed to program in under 5 minutes

DIRECT REPLACEMENT: Fit, form and function

Direct/FIT



CONVENIENCE



DO-IT-YOURSELF PROGRAMMING

Simple plug and play programming tool takes only minutes to sync Dorman remote to the vehicle



Ford Trucks and SUVs 2013-98

NEW 13745 Buick, Chevrolet, GMC, Oldsmobile, Pontiac Sedans 2007-01



13731 Buick, Chevrolet, Pontiac, Saturn Sedans 2012-04



57001 A variety of GM SUVs 2015-10

DVD PLAYER REMOTE

Have you lost or broken your vehicle's DVD remote?

This replacement brings back the convenience of watching movies in your vehicle, and restores peace and quiet on long road trips **10-0500F** Universal

HEADPHONES

Automatically syncs to vehicle's entertainment systems for easy use

Includes auxiliary jack to connect to MP3 players and smartphones





5

CONVENIENCE

TOUCH SCREEN INFOTAINMENT DISPLAYS

Remanufactured to address internal solder issues in original design

PLUG AND PLAY: Easy install, no programming required

Restores navigation, audio, climate, info display functionality



599-943 Toyota Prius 2009-04 without navigation



601-001 Grand Cherokee, Commander 3.7L 2007-05

SHIFT INTERLOCK MODULE

Prevents vehicle from starting in any gear other than park or neutral

REDUCE REPAIR COST: Replace just the failed part instead of the entire shifter assembly



Failure Mode: Inability to shift out of park

590-002 GM CK Truck Series 2006-03

POWER SEAT CONTROL MODULE

599-942

Toyota Prius 2006-04 with navigation

> DORMAN ENGINEERED: Modulos are designed

Modules are designed with higher tolerance components to reduce static shock



Failure Mode: Static charge or module overheating causes a loss of ability to control one or more seat functions



BLIND SPOT DETECTION MODULE

Detects objects and vehicle's in close proximity to the drivers blind spot

Failure Mode: Corrosion/ water intrusion

INSTRUMENT CLUSTERS*

READY TO INSTALL: Fully programmed with mileage and VIN, no programming or scan tool required

Fully Remanufactured and Tested – All units include all new stepper motor designs and backlight bulbs

*Available in the U.S. only

Ground



CONVENIENCE

000 MPH 48 000

FREE GROUND SHIPPING Included with each order. Ships same

day if ordered by 3:30 p.m. EST.

599-337 Chevrolet Silverado, Suburban 2012-07, GMC Sierra, Yukon XL 2012-07



599-390 Cadillac 2002, Chevrolet 2002-00, GMC 2002-00



599-806 NEW Chevrolet 2002-00, GMC 2002-00

599-343 Chevrolet 2005-03, GMC 2005-03, Upgraded

SWITCHES -POWER WINDOW

Easy plug-and-play installation, no programming required

Fully remanufactured and tested for quality assurance

Failure Mode: Electrical and mechanical failure





901-291R Chevrolet 2013-07, GMC 2013-07 **901-296R** Cadillac 2006-03, Chevrolet 2007-03, GMC 2007-03, Hummer 2007-03

901-299R

Chevrolet Trailblazer 2009-06,

Chevrolet Trailblazer EXT 2006

901-298R Cadillac 2006-03, Chevrolet 2006-03, GMC 2006-03, Hummer 2004-03

901-295R Chevrolet Trailblazer 2004-02, Chevrolet Trailblazer EXT 2004-0



CONVENIENCE

C

0

PASS

HVAC **CONTROL** MODULES

READY TO INSTALL: Plug and play design requires no programming

Fully Remanufactured and Tested - Includes backlight replacement bulbs and O-Rings (where applicable)

Failure Mode: Burnt out bulbs, fan and temperature control failure





599-196 Chrysler 300 2010-06, Dodge Charger 2010-06, Dodge Magnum 2008-06

599-144

Buick Enclave 2012-08, Chevrolet Traverse 2012-09



Jeep Grand Cherokee 2004-02



586-005 Ford Taurus 2007-04, Mercury Sable 2005-04



EASY TO INSTALL: No programming required

DORMAN ENGINEERED: Upgraded with an auxiliary jack for easy connection to smart phones and MP3 players (where applicable)

DIRECT REPLACEMENT: Fit, form and function



NVFR

VAII ARI F



Failure Mode: Original bulbs burn out or electrical failure; Failure results in a dark display and improper radio functioning

ALSO AVAILABLE

586-012 Chrysler 2000-97, Dodge 2002-97, Eagle 1997, Jeep 2002-96, Jeep 1993, Plymouth 2000-97

586-007 Ford 2005-98, Mazda 2003-99, Mercury 2001-98

586-006 Ford Taurus 2003-01, Mercury Sable 2003-01



586-025 Chrysler 2010-05, Dodge 2010-04, Jeep 2010-05, Mitsubishi 2008-06



586-022 GM 2005-95, ISUZU 1999-98



POWERTRAIN & 4WD



DIESEL GLOW PLUG CONTROLLER

Glow plug controllers are vehicle simulator tested for durability and quality assurance

DORMAN ENGINEERED: Improved design allows diagnosis of individual glow plugs





Failure Mode: Failed circuit within the module

ALSO AVAILABLE

904-304 Dodge Sprinter 2500 2006-03, Dodge Sprinter 3500 2006-03

904-282 Ford 2010-03, Ford 2001-00 **904-310** Sprinter, Freightliner, Jeep, Mercedes 3.0L Diesel 2015-05



341-5001 Detroit Diesel Series 60, 16, 15, 13 Engines 2015-87

THROTTLE BODY MOTOR

Completely remanufactured and tested for durability and performance

EXCLUSIVE

Failure Mode: Throttle sticks or is non-responsive due to carbon build up



599-5001 Cummins ISX 15.0, Cummins ISM 10.8 2007-05

TURBO AIR CONTROL VALVE

Controls the pressurized air (60psi) going to the pneumatic turbo actuator which in turn controls the turbo boost pressure

100% replacement of seals and grommets with upgraded nylon designs

EXCLUSIVE

Failure Mode: Carbon build-up on the plunger

601-016 NEW Grand Cherokee, Ram, Dakota 2007-00

AUTO TRANS PRESSURE SENSOR TRANSDUCER

PLUG AND PLAY: Easy installation without the need for programming

Failure Mode: Original internal sensor fails



POWERTRAIN & 4WD

917-030 BMW 2012-08

ECCENTRIC SHAFT SENSOR

Detects angle of eccentric shaft

- Direct replacement for popular **BMW** application
- Housing material upgraded to prevent oil intrusion

Failure Mode: oil leaks into electronics. Failure results in vehicle misfire and illumination of check engine light

TURBOCHARGER VANE POSITION SOLENOID

Determines the position of the turbocharger vane

Replacement of a failed sensor prevents loss of engine power and potential wear and tear to the vehicle's turbo system

Failure Mode: Carbon build up causes the original sensor to stop functioning properly

> 904-235 NEW GM 6.6L Diesel Vehicles 2015-06

904-219 Ford 6.0L Diesel Engines 2010-03

EGR VALVE

100% New, not remanufactured **PLUG AND PLAY:** No programming required

Failure Mode: Carbon build up causes piston to seize



•

POWERTRAIN & 4WD

599-112 NEW

599

Cadillac Escalade 2007, Chevrolet Silverado 2007,

GMC Sierra, Yukon 2007



TRANSFER CASE CONTROL MODULES

Fully remanufactured and vehicle simulator tested for quality assurance

REDUCE REPAIR COST: Dorman unit does not require programming, saving the time and money associated with a trip to the dealer

Completely remanufactured and tested



Failure Mode: Corrosion over time



NEW 599-192 Chevrolet Silverado/Tahoe 2013-07, GMC Sierra, Yukon 2014-07 with RPO Code NQH



NEW 599-250 Buick Rainier 2007-06, Chevrolet Trailblazer 2009-06, GMC Envoy 2009-06



mmmm

599-114 Chevrolet 2007-03, GMC 2007-03



FUEL PUMP DRIVER MODULE

PLUG & PLAY: for easy installation

DORMAN ENGINEERED: Improved micro-processor to provide greater response time and reliability



Failure Mode: Loss of electrical connection





BODY CONTROL

502-009

BODY **CONTROL MODULES**

Fully remanufactured and tested for durability and quality assurance

100% replacement of fuses, relays, resistors, capacitors and soldering joints (where applicable)

Failure Mode: Original unit fails due to excessive heat, shock, movement or mechanical wear



502-009 Chevrolet Malibu 2005-04, Pontiac G6 2005



502-008 Chevrolet 2007-03, GMC 2007-03



502-000 Cadillac 2011-07,

Chevrolet 2011-07, GMC 2011-07

INTEGRATED CONTROL MODULES

ALSO KNOWN AS: TOTALLY INTEGRATED POWER MODULE (TIPM)

Fully remanufactured and vehicle simulator tested for quality assurance

Failure Mode: Internal circuit failure causes erratic electrical problems in original unit

> 599-924 Dodge Ram 2500 2006, Dodge Ram 3500 2006

599-914 NEW Dodge Ram 2500 2009-08, Dodge Ram 3500 2009-08

599-909 Chrysler PT Cruiser 2009-06




502-001

Chevrolet 2012-06,

Pontiac 2009-07, Saturn 2010-07

GMC 2012-07.

502-007 Chevrolet 2007-03 GMC 2007-03, Hummer 2007-06



• NEW SINCE 1918

COMPLEX ELECTRONICS • THE LEADER IN FORMERLY "DEALER ONLY" PARTS

HYBRID

ELECTRIC MOTOR TRANSMISSION STATOR

Provides energy to help power the drive motor

REDUCE REPAIR COST: Replace just the failed stator instead of the entire assembly, saving up to 5 hours in labor costs.

Includes removable alignment studs to assist with installation.



Failure Mode: Vibration, friction, contamination and heat cause the original windings insulation to breakdown, short and burn out

NEW 587-990 Toyota Prius 2003-01

DRIVE MOTOR INVERTERS

Restores hybrid operation and drivability of vehicle

Replacement protects against potential damage to other hybrid system components

Fully remanufactured and vehicle tested for performance and quality assurance

Failure Mode: Failure results in reduced hybrid system performance, and illumination of check engine light



587-900

Toyota Prius 2003-01

ALSO AVAILABLE

587-901 NEW Toyota Prius 2009-04

> **587-022** Lexus GS450h 2011-07, Toyota Camry 2011-07

HYBRID BATTERY SERVICE PLUGS

Safety plug for hybrid drive batteries to ensure voltage is not transmitted when plug is removed

Compatible with Dorman's hybrid drive batteries

Failure Mode: Lost or blown fuse; Failure results in battery not functioning properly

587-020 Lexus RX400h 2008-06, Toyota Highlander 2008-06, Toyota Prius 2003-01

587-021 Lexus LS600h 2009-08, Toyota Prius 2009-04







587-013 Ford Escape 2009-05, Mercury Mariner 2009-06

587-010 Nissan Altima 2011-07



ALSO AVAILABLE FROM DORMAN



QUALITY • INNOVATION • VALUE

DORMAN LEADING VVT TECHNOLOGY SOLUTIONS

Comprehensive Coverage for both Variable Valve Timing Solenoids and Camshaft Phasers High Quality Replacement Parts | Coverage for Import and Domestic Applications

VARIABLE VALVE TIMING SOLENOIDS

OVER 75 SKUS COVERING OVER 83 MILLION REPAIR OPPORTUNITIES

917-224

917-219

GM 2010-04

CAMSHAFT PHASERS

OVER 15 SKUS COVERING OVER 24 MILLION REPAIR OPPORTUNITIES

917-255 Buick 2004, Chevrolet 2004-02. GMC 2004-02, Isuzu 2004-03, Oldsmobile 2004-02

> 917-257 Toyota Celica 2005-00, Corolla 2008-98,

Matrix 2008-03, MR2 Spyder 2005-00

ALL COMPONENTS UNDERGO EXTENSIVE TESTING TO ENSURE DORMAN QUALITY | PRECISION FIT | DURABILITY | PERFORMANCE



Acura 2006-02, Honda 2011-02





- BACKED BY DORMAN'S LIMITED LIFETIME WARRANTY -



DOR75544-1