CARDONE

WE BUILD IT BETTER

New Products & Innovative Solutions for Automotive Technicians



Rear Drive Axle Assemblies

Save time & money with COMPLETE BOLT-ON READY Axles

Bolt-on Ready

No need for a repair specialist or a lengthy, complicated rebuild. CARDONE's full assemblies are available in open or limited slip differentials and various ratios. All units are 100% pressure and load tested and come pre-filled with oil.

No-Hassle Delivery & Core Return Process

We will handle all delivery and core pick up logistics to and from your shop — **FREE OF CHARGE!**



100% New U-Bolt Kits

Each kit contains two U-bolts with nuts and washers and has a rust-resistant coating for longevity.



Average axle rebuild time: 6 - 10 hours CARDONE axle installation time: 2 hours!



3A-17006MSJ - New Offering! 2001-04 Jeep Grand Cherokee



3A-17008MOJ - New Offering! 1997-2002 Jeep Wrangler



3A-18000LOC - High Demand! Available Only at CARDONE!

1999-2004 Chevrolet Silverado 1500, GMC Sierra RWD and w/o Limited Slip Differential and w/ 3.08 Axle Ratio



3A-18000LHJ - High Demand! 1999-2005 Chevrolet Silverado 1500, GMC Sierra w/Limited Slip Differential and w/ 3.73 Axle Ratio



3A-17000LSW - High Demand!

2002-07 Dodge Ram 1500 Pickup 4WD and w/ Limited Slip Differential and w/ 3.92 Axle Ratio



3A-2000LSJ - Available Only at CARDONE!

2005-07 Ford F-250/350 Super Duty w/ Single Rear Wheels and w/ Limited Slip Differential and w/ 3.73 Axle Ratio

25 SKUs

Electronic Throttle Body Assemblies

Best coverage, best prices, exclusive application offerings!



67-4012 - Available Only at CARDONE! 2010-16 Audi S5/S4 V6 3.0L



67-5006 - Available Only at CARDONE! 2013-15 Mercedes E350 V6 3.5L

100% New

Electronic Throttle Body Assemblies

A cost effective alternative to 0.E.



6E-7002 - High Demand! 2007-17 Jeep Trucks; Dodge/Chrysler 2.4 L Vehicles



6E-0014 - High Demand! 2007-17 Nissan Vehicles



6E-0012 - High Demand! 2004-10 Infiniti Trucks; 2004-17 Nissan Trucks



6E-6008 - High Demand! 2005-07 Ford/Mercury Vehicles

Troubleshooting Electronic Throttle Bodies

The Electronic Throttle Body (ETB) is part of the Throttle-By-Wire System. It is important to check the whole system prior to any repairs.

The ETB Controls the amount of air flow that enters the intake manifold of the engine.



Symptoms of a failed/failing ETB are:

Hesitation, Sag, Stumble

There is a momentary lack of response as the accelerator is pushed down. This condition can occur at any vehicle speed. This condition is usually more pronounced when first trying to make the vehicle move, as from a stop. This condition may cause the engine to stall in severe conditions.

Lack of Power, Sluggishness, or Sponginess

The engine delivers less than expected power. There is little or no increase in speed when the accelerator pedal is pushed down part way.

Surges/Chuggles

Engine power varies under steady throttle or cruise. It feels like the vehicle speeds up and slows down with no change in the accelerator pedal position.

Note: After cleaning or replacing a heavily coked throttle body, a Throttle Body Relearn procedure will need to be performed. (Follow O.E. procedure).

Comment: Ensure weather seal on ETB Connector is not missing or damaged. If so, water entry can damage the internal components of the unit.

After replacing the ETB, always follow proper relearn procedures as required by the manufacturer.



Instrument Clusters

Showroom quality look and precise function at a fraction of the market price!



2L-1000, 2L-1001, 2L-1002, 2L-1209 **High Demand!** 2003-07 Chevrolet/GMC Trucks, A/T, 6 Gauge*



2L-1004, 2L-1067, 2L-1068, 2L-1210 **High Demand!** 2003-07 Chevrolet/GMC Trucks, A/T, 7 Gauge*



2L-1013, 2L-1036, 2L-1090, 2L-1095 High Demand! 2002-09 Chevrolet Trailblazer*



2L-2000 *2005 Ford Mustang*



2L-1008, 2L-1069, 2L-1070, 2L-1214 2003-07 Chevrolet/GMC Trucks, A/T, 7 Gauge, Diesel*



2L-1024, **2L-1073**, **2L-1098**, **2L-1029** 2002-09 GMC Envoy, 6 Gauge w/ DIC*

Brand-new or restored lens enhances visibility

Better-than-O.E. upgraded, gear-driven stepper motors

Pre-programmed with VIN, mileage, and engine hours, where applicable

Remanufactured in the U.S.A.

4 SKUs

Climate Control Modules

Plug and play installation with no programming required!



4C-1000 2003-07 Chevrolet/GMC Trucks



4C-1003 - High Demand! 2007-11 Chevrolet/GMC Trucks



4C-1005 2008-12 Buick Enclave, Chevrolet Traverse



4C-1006 2008-12 GMC Acadia

Unit face is restored to O.E. appearance and functionality.

Electronic repair components are upgraded to meet or exceed O.E. design.

100% functional testing performed to deliver guaranteed performance and reliability.

100% New

Camshaft Phasers

41 SKUs

Plug and play installation!



7V-1000P - High Demand! 2006-17 Chevrolet/GMC



7V-1005P - High Demand! 2006-17 Chevrolet/GMC

Hybrid Batteries

Outperform and outlast any aftermarket brand — backed by industry-leading warranty!



5H-4002 - High Demand! 2004-09 Toyota Prius GEN 2



5H-4003 *2009-11 Toyota/Lexus GEN 3*



2007-11 Toyota Camry



2012-15 Toyota Camry, Lexus ES300H



5H-5001 2003-05 Honda Civic



5H-5002 *2006-11 Honda Civic*

Entire battery pack balanced to ensure each module operates at consistent efficiency

ECU 100% replaced and 100% tested to ensure battery does not fail

Relays 100% tested, which is critical to ensure long-lasting battery life

New and Remanufactured

Diesel Exhaust Fluid Pumps

Plug-and-play design makes installation a snap!



5D-1000 - High Demand! 2010-16 Chevrolet/GMC 6.6L Trucks



5D-3002 - High Demand! 2010-12 Dodge Ram 3500, 4500, 5500

Remanufactured in the U.S.A.

10 SKUs

5 SKUs

Diesel Exhaust Fluid Heating Pots

A cost effective alternative to the O.E. dealer!



5D-1001L - Available Only at CARDONE! 2011 Chevrolet Silverado 2500HD/3500HD, GMC Sierra 2500HD/3500HD



5D-1003L - Available Only at CARDONE! 2012-16 Chevrolet Silverado 2500HD/3500HD, GMC Sierra 2500HD/3500HD



5D-9007L - Available Only at CARDONE! 2015-16 Mercedes Trucks



5D-9011L - High Demand! 2012-14 Volkswagen Passat

100% New

Air Suspension Valve Blocks

Guaranteed to fit and function like the original – at a fraction of the typical market price.



4J-2004V 2007-14 BMW X6, X5



4J-2012V - Available Only at CARDONE! 2009-15 BMW 7 Series



4J-4002V 2006-17 Audi, Mercedes



4J-8000V - Available Only at CARDONE! 2003-17 VW/Audi/Porsche/Jeep

100% New

Air Suspension Compressors

A comfortable ride for years to come – at a fraction of the typical market price.



4J-0003C - High Demand! 2000-17 GM Trucks



4J-1005C 1997-2006 Ford Trucks

Full-Line Air Suspension Program



Struts



Springs



Compressors



Compressor Dryers



New and Remanufactured

Air Suspension Springs & Struts

Built to withstand harsh road conditions and tested to ensure O.E. performance.



4J-1007A - High Demand! 1990-2011 Ford Crown Vic Family - Rear



4J-5000A - High Demand! 2002-09 GM Trucks - Rear



4J-0005S - High Demand! 2000-17 GM Trucks - Rear



4J-2006S - High Demand! 2004-12 Mercedes Trucks - Front

100% New

Air Suspension Conversion Kits

Convert air suspension systems to a cost-effective coil spring solution.



4J-1011K 1990-2011 Ford Crown Vic Family – Rear



4J-6001K 2003-09 Toyota/Lexus Trucks – Rear

280 SKUs



Ride Height Sensors



Shock Absorbers



Solenoids



Valve Blocks

100% New 310 SKUs

Power Steering Pumps & Racks


Lowest comeback rate in the aftermarket - at a fraction of the O.E. price!



100% New

Hydraulic Transfer Tubing

Save money by replacing a damaged line only – no need to replace the entire rack!



40 SKUs

100% New

Power Steering Pump Pulleys

Direct-fit, easy installation!



3P-25160 - High Demand 1987-2016 Chevrolet, Buick, Cadillac, GMC



40 SKUs

3P-25140 - High Demand 1980-2006 Ford, Merc, Lincoln



3P-35133 - High Demand 2001-07 Chrysler, Dodge

100% New

Power Steering Pump Remote Reservoirs

O.E. design match, including reservoir cap



3R-216 - High Demand 2001-05 Acura. Honda



3R-102 - High Demand 2002-12 Lexus, Toyota



3R-202 - High Demand 2003-12 Acura. Honda

100 SKUs