



HOLIDAY NEW PRODUCT PROMOTION



Take advantage of over 80 NEW items introduced this year with additional savings!

Place your orders today on our estore or through our customer service team.



NEW Automotive Units

11061N

Alternator-DR IR/LC
190 Amp/12 Volt, CW, 7-Groove Clutch Pulley
Replaces: Audi, Volkswagen 021-903-026K, 07C-903-021G, & more
Used on: Porsche (2004-2006), Volkswagen (2004-2007), & more
Lester: 11061

11406N

Alternator-ND IR/IF
180 Amp/12 Volt, CW, 6-Groove Pulley
Replaces: Denso 104210-6170, Lexus 27060-38060
Used on: Lexus (2008-2014)
Lester: 11406

11407N

Alternator-ND IR/IF
130 Amp/12 Volt, CW, 6-Groove Clutch Pulley
Replaces: Denso 104210-2360, 104210-2361, 104210-2362, TN104210-2362, Toyota 27060-0V030
Used on: Toyota (2009-2015)
Lester: 11407

11441N

Alternator-MI IR/IF
12 Volt, 150 Amps, CW, S7
Replaces: Mitsubishi A002TX0091, Nissan, Infiniti 23100-JF01A
Used on: Nissan (2009-2018)
Lester: 11441

11513N

Alternator-ND IR/IF
150 Amp/12 Volt, CW, 6-Groove Pulley
Replaces: Denso 104210-5400, GM 23480515, 25925447
Used on: Cadillac (2009-2015)
Lester: 11513

11541N

Alternator-MI IR/IF
12 Volt, 150 Amps, CW, S6
Replaces: Mitsubishi A002TX1591, Nissan, Infiniti 23100-1ZA1A
Used on: Infiniti (2011-2018)
Lester: 11541

11552N

Alternator-MI IR/IF
12 Volts, 140 Amps, CW, SC6
Replaces: GM 92254672, 92421122, Mitsubishi A002TX3781, A002TX3981, A2TX3781
Used on: Chevrolet (2014-2016)
Lester: 11552

11554N

Alternator-MI IR/IF
12 Volt, 160 Amps, CW, SD6
Replaces: Chrysler 56029624AA, 56029624AB, Mitsubishi A002TX3581ZE
Used on: Chrysler (2015-2017), Fiat (2016-2018), Jeep (2014-2018), Ram (2015-2018)
Lester: 11554



The latest product technology from WAI

11600N



Alternator-ND IR/IF
120 Amp/12 Volt, CW, 6-Groove Decoupler Pulley
Replaces: Denso 104210-1600, TN104210-1600, Honda 31100-R70-A11, 31100-R70-A11RM
Used on: Honda (2011-2012)
Lester: 11600

11609N



Alternator-VA IR/IF
12 Volt, 110 Amps, CW, SD6
Replaces: Hyundai 37300-2B760, 37300-2B760RU, Kia 37300-2B760, 37300-2B760RU, Valeo 2616559
Used on: Hyundai (2013-2017), Kia (2012-2017)
Lester: 11609

11626N



Alternator-ND IR/IF
150 Amp/12 Volt, CW, 6-Groove Pulley
Replaces: Denso 104210-2950, TN104210-2950, Ford BR3Z-10346-E, Ford Engineering BR3T-10300-LA
Used on: Ford (2011-2014)
Lester: 11626

11644N



Alternator-MI IR/IF
170 Amps/12 Volts, CW, SD6
Replaces: GM 92259199, Mitsubishi A003TX1081, A3TX1081
Used on: Chevrolet (2012-2016)
Lester: 11644

11701N



Alternator-VA IR/IF
150 Amps/12 Volts, CW, SC6
Replaces: Hyundai 37300-2E800, Valeo 2619086
Used on: Hyundai (2014-2016)
Lester: 11701

11873N



Alternator-MI IR/IF
12 Volt, 250 Amps, CW, S6
Replaces: Ford FL1Z-10346-A, FL1Z-10346-B, Ford Engineering FL1T-10300-AA, FL1T-10300-AB, & more
Used on: Ford (2015-2017), Lincoln (2015-2017)
Lester: 11873

11917N



Alternator-MI IR/IF
210 Amp/12 Volt, CW
Replaces: Ford GB5Z-10346-B, Ford Engineering GB5T-10300-BB, Mitsubishi A003TV0791, A003TV0791ZC
Used on: Ford (2014-2018)
Lester: 11917

20082N



Alternator-MI IR/IF
12 Volts, 105 Amps
Replaces: Honda 31100-5R7-A01, 31100-5R7-A01RM, 31100-5R7-A02, 31100-5R7A-A010-M2, AHGA95, Mitsubishi A005TZ0281ZC
Used on: Honda (2015-2016)
Lester: 20082

20084N



Alternator-MI IR/IF
12 Volt, 105 Amps, CW, S6
Replaces: Honda 31100-5R0-004, 31100-5R0-004RM, 31100-5R0-014, AHGA92, Mitsubishi A005TZ0291ZC
Used on: Honda (2015-2016)
Lester: 20084

21151N



Alternator-MI IR/IF
105 Amp/12 Volt, CW
Replaces: Honda 31100-50Z-G01, AHGA103, Mitsubishi A005TZ0091A
Used on: Honda (2017-2018)
Lester: 21151

21152N



Alternator-MI IR/IF
150 Amp/12 Volt, CW, S7
Replaces: Mitsubishi A003TJ4691, Nissan, Infiniti 23100-9UA0A
Used on: Infiniti (2017-2018), Nissan (2016-2018)
Lester: 21152

21153N



Alternator-VA IR/IF
130 Amps/12 Volts, CW, SD6
Replaces: Hyundai 37300-2B960, Kia 37300-2B960, Valeo 2622503
Used on: Hyundai (2015-2018), Kia (2016-2016)
Lester: 21153



NEW Non-Automotive Units

The latest product technology from WAI

23876N



Alternator-BO IR/IF 110 Amp/24 Volt

Replaces: Bosch 0 124 655 012, 0 124 655 019, Prestolite 860804, 860804GB, Renault 5010589551, 7420466317, 7420862899, Volvo 20466317, & more
Used on: Volvo (2005-2007)
Lester: 23876

12579N



Alternator-BO IR/IF 120 Amp/12 Volt, S8

Replaces: Bosch 0 124 515 120, Case 47129299, New Holland 47129299
Used on: Case (2004-2015), New Holland Industrial (2004-2015)
Lester: 12579

11305N



Alternator-BO IR/IF 220 Amp/12 Volt, CW, S6

Replaces: Bosch 0 121 813 001, 0 121 813 014, 0 121 813 101, 0 121 813 114, Chrysler 68011843AA, & more
Used on: Caterpillar Ag. & Ind. (2013-2016), Dodge (2007-2008), & more
Lester: 11305

11907N



Alternator-BO IR/IF 130 Amp/24 Volt, CW

Replaces: Bosch 0 124 655 080, 0 124 655 191, 0 124 655 192, John Deere RE538907, RE558679, SE502564
Used on: John Deere (2012-2014)
Lester: 11907

21211N



Alternator-DR 13SI IR/IF 100 Amp/12 Volt, CW

Replaces: Caterpillar 20R3598, 321-8902, Delco 8600375
Lester: 21211

21127N



Alternator-DR 13SI IR/IF 75 Amp/24 Volt, CW

Replaces: Caterpillar 20R-3890, 234-3463, 399-1485, Delco 8600573, 8600686, Perkins Engine 3991485
Used on: Caterpillar Ag. & Ind. (1995-2014)
Lester: 21127

8754N



Alternator-DR 40SI 275 Amp/12 Volt, CW

Replaces: Delco 8600279
Lester: 8754

8759N



Alternator-DR 40SI 320 Amp/12 Volt, CW, w/o Pulley

Replaces: Delco 8600634
Used on: Intl/Mack/Sterling/Thomas with 320 amp alternators
Lester: 8759

8912N



Alternator-DR 40SI 320 Amp/12 Volt, CW

Replaces: Delco 8600628
Lester: 8912

12278N



Alternator-HI IR/EF 50 Amp/12 Volt

Replaces: Hitachi GD207976-A, LR150-165, Hyster 1360815, 3068340, 3122810, Isuzu 5812003470
Used on: Daewoo (1997-2000), Isuzu (1983-1993), J.C. Bamford (1996-2000)
Lester: 12278

12042N



Alternator-HI IR/IF 60 Amp/12 Volt, CW

Replaces: Hitachi LR160-741, Yanmar 128271-77200
Used on: Yanmar (1994-2003)
Lester: 12042

14887N



Alternator-IK IR/EF 120 Amp/12 Volt, CW, V1

Replaces: Case 84281043, CNH Industries 84281043, Fiat 84281043, Letrika (Iskra) 11.204.635, & more
Used on: Case (2011-2015), New Holland Industrial (2013-2013)
Lester: 14887



NEW Non-Automotive Units

The Power of WAI

The latest product technology from WAI

20914N



Alternator-IK IR/EF
95 Amp/12 Volt, CW
Replaces: Deutz Engine Mfr 0118 2968, 0118 3439, 0118 3624, 0118 3842, Letrika (Iskra) 11.204.463, Letrika Old 11.203.524, 11.204.708
Used on: Linde/Deutz forklifts
Lester: 20914

20723N




Alternator-IK IR/IF
120 Amp/12 Volt, CW
Replaces: Agco Sisu Power 4287014M1, Letrika (Iskra) 11.203.828
Used on: Massey Ferguson (2008-2015)
Lester: 20723

21351N



Alternator-IK IR/IF
150 Amp/12 Volt, CW
Replaces: Bosch 0 123 510 060, DAF 1340893, Fendt G 515 900 010 100, KHD 0118-0758, 118-0758, & more
Used on: Fendt (1980-2003), John Deere (1992-2005)
Lester: 12675, 21351

10944N



Alternator-KOK DENKI
35 Amp/12 Volt, 1-Groove Pulley
Replaces: John Deere AM877957, AM880339, Kokusan Denki GP9178
Used on: John Deere (1984-2002)
Lester: 10944

10943N



Alternator-KOK DENKI PM
12 Volt, V1
Replaces: Iseki 6281-200-032, 6281-200-032-10, Kokusan Denki GP9914
Used on: Iseki tractors
Lester: 10943

14050N



Alternator-LU IR/EF
43 Amp/12 Volt, CW, 1-Groove Pulley
Replaces: Lucas 23746, 23746A, 23749, 23756, 23756A, 23756D, 23806, 23806A, 23806B, 23832, 23832A, & more
Used on: Case (2001-2006), MG (1974-1978), MG - Europe (1975-1979), & more
Lester: 14050

12310N



Alternator-MI IR/EF
40 Amp/24 Volt, CW
Replaces: Case 135104A1, Mitsubishi A004T40287, Mitsubishi Heavy Industries ME049280
Used on: Case (1992-2003), Caterpillar Ag. & Ind. (1998-2007)
Lester: 12310

20882N



Alternator-MI IR/IF
80 Amp/12 Volt, CW
Replaces: Kubota 3N301-64011, 3R600-64010, 3R600-64011, 3R600-64012, Mitsubishi A005TA5977, A005TA5977B, A005TA5977C, & more
Used on: Kubota (2007-2016)
Lester: 20882

12734N



Alternator-MI IR/IF
50 Amp/12 Volt, CW, 1-Groove Pulley
Replaces: Mitsubishi A007TA0477, A007TA0477A, Mitsubishi Heavy Industries 32A68-10200
Used on: Mitsubishi (1994-2016)
Lester: 12734

12468N



Alternator-ND IR/EF
130 Amp/12 Volt, CW
Replaces: Delco 8600127, Denso 101211-8390, Kenworth D27-6001-0130P, Peterbilt Truck D27-6001-0130P
Used on: Freightliner/Mack/Intl/Kenworth tks
Lester: 12468

12865N



Alternator-ND IR/ER
105 Amp/12 Volt, CW
Replaces: Denso 101211-8421, 101211-8431, Hino 27040-2550, 27040-2550B, 27040-2560B, 27040-2560R
Used on: Hino (2005-2010)
Lester: 12865, 12866

10941N



Alternator-PM
15 Amps/12 Volt, PMA
Replaces: Yanmar 124660-77990, 124660-77991
Used on: 1976-1997 Yanmar tractors
Lester: 10941



NEW Non-Automotive Units

The latest product technology from WAI

18952N



Starter-BO PLGR
2.2kW/12 Volt, CW, 9-Tooth Pinion
Replaces: Bosch 0 001 218 176, John Deere FGV35532054, VM Motori 35532054F, Yale 50128567
Used on: John Deere (2008-2011)
Lester: 18952

5414N



Starter-DR 35MT PLGR
4.3kW/12 Volt, CW, 10-Tooth Pinion
Replaces: Delco 5267911, 8200371, 8200375, 8200834, 8200959
Used on: Ford (2008-2010)
Lester: 5414

5413N



Starter-DR 35MT PLGR
12 Volt, 4.3kW, CW, 12 Teeth
Replaces: Delco 5267908, 8200374, 8200836, 8200958
Used on: Freightliner/Kenworth/Sterling/Peterbilt/Bluebird/Ford/Intl 199-2015
Lester: 5413

31270N



Starter-DR PMGR
1.4KW/12 Volt, CW, 8-Tooth Pinion
Replaces: Clark 1242718, Delco 8000340, 8000925, Hyundai 36100-2CC00
Used on: Hyundai forklifts
Lester: 31270

18480N



Starter-IK DD
3.0kW/12 Volt, CW, 10-Tooth Pinion
Replaces: Agco Sisu Power 4507 008 8, 8366 620 73, D45070088, Bosch 0 001 359 124, 0 001 367 032, & more
Used on: Case (1997-2004), Massey Ferguson (1986-1986), & more
Lester: 18480

30685N



Starter-MI PMGR
12 Volt, 2.5kW, PMGR, 9-Tooth Drive
Replaces: Kubota 1G484-63001, 1G484-63011, Mitsubishi M008T71871, M008T71872, M008T71874
Used on: Kubota forklift and Carrier refrigeration units
Lester: 30685

18007N



Starter-ND OSGR
24 Volt/5.5kW, CW, 10 Teeth
Replaces: Cummins 3924466, Denso 228000-2200, 228000-2201
Used on: Case (1997-2010), Cummins Engines (1993-2003)
Lester: 18007

19201N



Starter-ND OSGR
3.0KW/12 Volt, CCW, 11-Tooth Pinion
Replaces: Denso 428000-5860, 428000-5861, 428000-5862, 428080-5863, & more
Used on: Chevy/GMC/Isuzu tks 2008-2017
Lester: 19201

16014N



Starter-ND PLGR
4.8KW/24 Volt, CW, 10-Tooth Pinion
Replaces: Denso 428000-6900, 428000-6901, 428000-9920, John Deere RE537519, RE539695, RE548693, RE549230, SE502559, SE502823
Used on: John Deere (2009-2015)
Lester: 16014

16096N



Starter-ND PLGR
2.7kW/12 Volt, CW, 10-Tooth Pinion
Replaces: Cummins 4996706, Denso 428000-7090, 428000-7091, 428000-7092, 438000-3110
Used on: 2.8/3.8/4.5/5.9/6.7 Cummins Ind engines
Lester: 16096

19856N



Starter-ND PLGR
3.0kW/12 Volt, CW, 10-Tooth Pinion
Replaces: Case 87638510, Denso 428000-6030, 428000-9910, 428000-9911, 428000-9912, New Holland 87638510, 87638510R
Used on: Case (2004-2012)
Lester: 19856

30691N



Starter-ND PLGR
3.0KW/12 Volts, CCW, 11-Tooth Pinion
Replaces: Denso 428000-5930, 428000-5931, 428000-5932, & more
Used on: Chevy/GMC/Isuzu truck 2008-2017
Lester: 30691



NEW Non-Automotive Units

The latest product technology from WAI

10955N



Starter-ND PLGR
2.7kW/12 Volt, CW, 11-Tooth Pinion
Replaces: Cummins 5256155, Denso 428000-6800
Used on: JLG Handlers
Lester: 10955

19335N



Starter-ND PLGR
3.0kW/12 Volt, CW, 11-Tooth Pinion
Replaces: Denso 428000-5310
Used on: Thomas Built Bus (2007-2016)
Lester: 19335

30693N



Starter-ND PLGR
24 Volt/7.8kW, PLGR, CW, 10-Tooth Drive
Replaces: Cummins 4996709, Denso 428000-7120, 438000-3730
Used on: 3.9/4.5/5.9/6.7 Cummins industrial engines
Lester: 16020, 30693

19945N



Starter-NK OSGR
5.5kW/24 Volt, CW, 10-Tooth Pinion
Replaces: Nikko 0-24000-3060, 02-24-2029
Lester: 19945

18088N



Starter-NK OSGR
7.5Kw/24 Volt, CW, 11-Tooth Pinion
Replaces: Komatsu 600-813-3610, 600-813-3730, Nikko 0-23000-6520, 0-23000-6521, 0-23000-6522, 0-23000-6523, 0-23000-6524
Used on: Komatsu (1986-2005)
Lester: 18088

18521N



Starter-NK OSGR
5.5kW/24 Volt, CW, 11-Tooth Pinion
Replaces: Komatsu 600-813-3320, 600-813-3321, 600-813-3360, Nikko 0-23000-1290, 0-23000-1291, 0-23000-1292, 0-23000-1293, 0-23000-1430
Used on: Komatsu (1986-2010)
Lester: 18521

19869N



Starter-NK OSGR
7.5Kw/24 Volt, CW, 11-Tooth Pinion
Replaces: Komatsu 600-813-7110, 600-813-7111, 600-813-7112, Nikko 0-23000-7160, 0-23000-7161, 0-23000-7162, 0-23000-7163, 0-23000-7770
Used on: Komatsu (1995-2005)
Lester: 19869

19942N



Starter-NK OSGR
24 Volt/3.0kW, OSGR, CW, 11-Tooth Drive
Replaces: Komatsu 600-863-3110, 600-863-3210, 600-863-3211, Nikko 0-24000-0030, 0-24000-0040, 0-24000-0041
Used on: Komatsu (1997-2015)
Lester: 19942

19951N



Starter-NK OSGR
7.5Kw/24 Volt, CW, 11-Tooth Pinion
Replaces: Mitsubishi Heavy Industries 37566-00500, Nikko 0-23000-7740, 0-23000-7741, 0-23000-7742, & more
Used on: Hitachi (2004-2008), Mitsubishi (1999-2009)
Lester: 19951

18130N



Starter-NK OSGR
5.5Kw/24 Volt, CW, 12-Tooth Pinion
Replaces: Komatsu 600-813-6210, 600-813-6211, 600-813-6212, Nikko 0-23000-2110, 0-23000-2111, 0-23000-2112, 0-23000-2113, & more
Used on: Komatsu (1986-2010)
Lester: 18130

18128N



Starter-NK OSGR
7.5Kw/24 Volt, CW, 13-Tooth Pinion
Replaces: Komatsu 600-813-3650, 600-813-3651, 600-813-4650, 600-813-4651, 600-813-4652, Lucas LRS01874, Nikko 0-23000-3170, 0-23000-3171, & more
Used on: Komatsu (1986-2010)
Lester: 18128, 19773

19775N



Starter-NK OSGR
24 Volt/4.5kW, OSGR, CW, 9-Tooth Drive
Replaces: Isuzu 8970789261, 8970789263, 8970789264, Nikko 0-23000-2200, 0-23000-2201
Used on: Isuzu (1996-2006)
Lester: 19775

The latest product technology from WAI

IX138



Voltage Regulator-Denso & Marelli IR-12 Volt, B-Circuit, Low Side Drive Regulator, 14.50 Vset
Replaces: Denso 126600-7240, MS126600-7240, Marelli CRE30118
Used on: Opel - Europe (2004-2015), Opel LCV - Europe (2004-2010), & more
Lester: 23958, 24063, 24064, 24065

M319



Voltage Regulator-VL 12 Volt, B-Circuit, High Side Drive Regulator, 14.5 Vset
Replaces: Hitachi 2500720, Valeo 593319
Used on: Mercedes - Europe (1998-2005)
Lester: 21465, 22850

DE1338



Voltage Regulator-DR B circuit, High Side Drive regulator
Replaces: Delco 10501338, 10535656
Used on: Delco 10532961, 19070007, 19070008
Lester: 8298, 8371, 8462

IK700



Voltage Regulator-Letrika (Iskra) IR/EF-12 Volt, B-Circuit, P-IGN-L Terminals, 14.46 Vset
Replaces: Letrika (Iskra) 16.915.561, Original Reference Number WG1789315
Used on: Case (2011-2015), New Holland Industrial (2013-2013)
Lester: 14887

M300



Voltage Regulator-VA LIN 12 Volt, B-Circuit, 14.3 Vset, LIN Terminals
Replaces: Valeo 2617441, 599239

M597



Voltage Regulator-VA 12 Volt, B-Circuit, High Side Drive Regulator, 14.3 Vset
Replaces: Valeo 593536, 593833
Used on: BMW - Europe (2000-2007)
Lester: 23249

IB6067



Voltage Regulator-BO 12 Volt, LIN Terminals, 14.3 Vset
Replaces: Bosch 0 272 220 804, 0 272 220 824, 0 272 220 854
Used on: Audi (2015-2017), Audi - China (2013-2015), Audi - Europe (2011-2018), Seat - Europe (2012-2017), & more
Lester: 20304, 20352, 20353, & more

IB731



Voltage Regulator-BO 12 Volt, B-Circuit, 14.4 Vset
Replaces: Audi, Volkswagen 03L 903 803 A, Bosch 0 272 220 701, 0 272 220 714, 0 272 220 720, & more
Used on: Citroen - Europe (2011-2016), Fiat - Europe (2006-2015), & more
Lester: 11563, 11723, 20544, & more

Part No.	Description	Specifications	Lester
IB855	Voltage Regulator-BO	12 Volt, B-Circuit, 14.3 Vset	20330, 20642, 20798, 20801, 20802, 20803
IK863	Regulator-Letrika (Iskra) IR/EF	12 Volt, A-Circuit	13204
IKR100	Rectifier-Letrika	12 Volt, 50 Amp Diodes	11839, 14034
IKR101	Rectifier-Letrika	12 Volt, 50 Amp Diodes	14887
IMR7500	Rectifier-MI	6-40Amp Diodes	12318
IMR85113	Rectifier-MI	24 Volt	11989, 11990, 12744
IHR788	Rectifier-HI	12 Volt	23098, 24027
IKR858	Rectifier-Letrika	12 Volt, 6-60A Avalanche Press Fit Diodes	12868A